

	Type	L #	Hits	Search Text	DBs	Time Stamp	Comments	Error Definition	Errors
1	IS&R	L1	1	("5700735").PN.	USPAT	2001/10/20 23:57			0
2	IS&R	L2	1	("6242813").PN.	USPAT	2001/10/21 00:06			0
3	BRS	L3	572	257/780.ccls.	USPAT; US-PGPGU B; EPO; JPO; DERWENT ; IBM TDB	2001/10/21 00:10			0
4	BRS	L4	181	L3 and terminal	USPAT; US-PGPGU B; EPO; JPO; DERWENT ; IBM TDB	2001/10/21 00:23			0
5	BRS	L5	996	257/784.ccls.	USPAT; US-PGPGU B; EPO; JPO; DERWENT ; IBM TDB	2001/10/21 00:23			0
6	BRS	L6	1066	257/786.ccls.	USPAT; US-PGPGU B; EPO; JPO; DERWENT ; IBM TDB	2001/10/21 00:24			0
7	BRS	L7	261	257/781.ccls.	USPAT; US-PGPGU B; EPO; JPO; DERWENT ; IBM TDB	2001/10/21 00:25			0
8	BRS	L8	114	438/666.ccls. and (pad or terminal)	USPAT; US-PGPGU B; EPO; JPO; DERWENT ; IBM TDB	2001/10/21 00:26			0
9	BRS	L9	118	bonds and (probe adj needle) and metal	USPAT	2001/10/21 00:29		Truncation Overflow. Return string from Server is: 5'0'0'BON	1

	Type	L #	Hits	Search Text	DBs	Time Stamp	Comments	Error Definition	Errors
1	IS&R	L1	1	("6110816").PN.	USPAT	2001/10/21 01:00			0
2	IS&R	L2	1	("6242813").PN.	USPAT	2001/10/21 01:12			0
3	BRS	L3	1	"5461008".PN.	USPAT	2001/10/21 01:01			0
4	BRS	L4	1	"5487999".PN.	USPAT	2001/10/21 01:01			0
5	BRS	L5	1	"5545589".PN.	USPAT	2001/10/21 01:01			0
6	BRS	L6	1	"5700735".PN.	USPAT	2001/10/21 01:01			0
7	BRS	L7	1	"5834365".PN.	USPAT	2001/10/21 01:04			0
8	BRS	L8	1	"5962919".PN.	USPAT	2001/10/21 01:07			0
9	BRS	L9	1	"5963831".PN.	USPAT	2001/10/21 01:07			0
10	BRS	L10	1	"6110816".PN.	USPAT	2001/10/21 01:07			0
11	BRS	L11	1	"5700735".PN.	USPAT	2001/10/21 01:08			0
12	BRS	L12	1	"5545589".PN.	USPAT	2001/10/21 01:08			0
13	BRS	L13	1	"5487999".PN.	USPAT	2001/10/21 01:08			0
14	BRS	L14	404	438/612.ccls.	USPAT	2001/10/21 01:13			0
15	BRS	L15	94	438/617.ccls.	USPAT	2001/10/21 01:13			0